



— WIRING DIAGRAM

PORTLAND

PLYMOUTH





PROVINCIAL. MET HOURLY RENTERS. MET.






CABLES DIRECT TO PROV. TEST I.D.F.

INSTRUMENTS.




LINES.



MET. TIME REP. 1. Cables R. GONGS. LINES. RETN. SHIP 101-105.



INSULATED.



C.T.O. CHRONOPHER -

Time of Control Clock operation
Diagram G.M.T. 18.




Figure 4